

Air-Tech's Fabric Covering Systems are Easy!

Covering with **AIR-TECH** materials is very easy. The labor is cut by almost one half compared to using dope. Little sanding is required for a smooth high gloss finish and AIR-TECH kits include all materials necessary for the job. Follow AIR-TECH's four easy steps.



1. Cover the aircraft with heat-shrinkable polyester fabric.



2. Spray three "wet" cross coats of the AIR-TECH primer.



3. After primer cures sand lightly.



4. Spray 2-3 coats of the AIR-TECH color of your choice.



LET IT DRY, ASSEMBLE, AND FLY IT!!!

APPLY IN ALMOST ANY WEATHER

The **AIR-TECH** system is not prone to "blushing" in humid or rainy weather. You can apply the material in temperatures as low as 45 degrees F or as high as 95 degrees F.

EASY TO REPAIR

If the skin is accidentally punctured, repairs are easy. Lightly sand around the damaged area; clean with solvent; apply a fabric patch using AIR-TECH adhesive. Prime and paint making the repair almost invisible.